

**TO BE FILLED BY THE INSPECTING OFFICER**  
**(ASSISTANT ENGINEER)**


1. Name of Officer : Jisha M V
2. Name of School : Chinmaya Vidyalaya
3. Location/with name of Education District/Sub District : Kalladathur /Ottappalam/Thrithala
4. Classification of building and size : Permanent
  1. Block 1- 32.3mX5.25X13.5m
  2. Block 2-28.56mX8.88mX13.5m
5. Period of which the certificate issued : 2023-2024
6. Nature of defects if any
  - a) Foundation and basement : Nil
  - b) Superstructure : Nil
  - c) Doors & windows : Nil
  - d) Wood work wrought and put up : Nil
  - e) Roof : Nil
  - f) Flooring : Nil
  - g) Miscellaneous (cracks etc) : Nil
7. Any major defects noticed which will Render the building unsafe in any manner: Nil
8. Whether maintenance works have been Done properly : Yes
9. Whether the structure is sound on for Conducting classes : The Structure is sound for conducting classes under normal weather condition.

Note: 1. The stability of the structure should be examined also with-reference to location, Attitude,intensity of wind, exposure to flood etc.  
2. Any additional observations if deemed necessary for the certificate may be furnished seperately with the certificate.

Certified that the school was inspected by me on 12/06/2023 and found to be fit to conduct classes for the period 2023-2024 for the reasons noted above.


Place: Kumaranellur

Date: 12/06/2023

Signature: 

Designation:

**ASSISTANT ENGINEER**  
**ISGD Section**  
**KAPPAD**

  
**MANAGER**  
**CHINMAYA VIDYALAYA**  
**KALLADATHUR**



  
**Principal**  
**Chinmaya Vidyalaya**  
**Engineer Road, Pilakkavu**  
**Kalladathur-679 552, Palakkad (Dist.)**