

TO BE FILLED BY THE INSPECTING OFFICER

Assistant Engineer

No:-48/AE/LSGD/KPR/25-26

1. Name of School : Chinmaya Vidyalaya
2. Location/with name of Education
District/Sub District : Kalladathur /Ottappalam/Thrithala
3. Classification of building and size : Permanent
 1. 20'x20'x11'9'' -12 Class Room
 2. 20'x40'x11'9'' -6 Class Room
 3. 30'x18'x10' -1 Class Room
 4. 26'x15'x10' -1 Class RoomAll Are Post KER
4. Period of which the certificate issued : 2025-2026
5. Nature of defects if any
 - a) Foundation and basement : Nil
 - b) Superstructure : Nil
 - c) Doors & windows : Nil
 - d) Wood work wrought and put up : Nil
 - e) Roof : Nil
 - f) Flooring : Nil
 - g) Miscellaneous (cracks etc) : Nil
6. Any major defects noticed which will
Render the building unsafe in any manner: Nil
7. Whether maintenance works have been
Done properly : Yes
8. Whether the structure is sound on for
Conducting classes : The Structure is sound for conducting classes
under normal weather condition.

Note: 1. The stability of the structure should be examined also with reference to location, Attitude,intensity of wind, exposure to flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished seperately with the certificate.

Certified that the school was inspected by me on 06/10/2025 and found to be fit to conduct classes for the period 2025-2026 for the reasons noted above.

Place: Kumaranellur

Date: 10/10/2025

Signature:



Designation:



ASSISTANT ENGINEER
LID & EW SECTION
KAPPUR GRAMA PANCHAYATH